

## DEALER PARTS and SERVICE BULLETIN

Hap Alzina

3074 Broadway


Oakland 11, Calif.

INDEX

No. 99 17 DEC 1963

= SUBJECTS =

FITTING OF OIL UNION GASKET ALL B40 AND "C" SERIES MODELS



## = IMPORTANT =

IT IS IMPORTANT THAT THE FITTING OF OIL PIPE UNION (Feed and return line assembly) GASKET NO. 40-0204 BE CHECKED ON EASH ASSEMBLY TO BE SURE THE GASKET HAS NOT BEEN RE-VERSED.

GASKET NO. 40-0204 IS NOT A "MIRROR" GASKET (i.e. it is not the same if reversed).
INSTALLING IT UPSIDE DOWN WILL RESULT IN CLOSING OFF HALF OF THE OIL FEED AND OIL RETURN HOLES.

The middle hole for the affixment stud is not exactly in the center with the result that the gasket can be reversed accidentally and will still permit the union being drawn up BUT WITH THE RESULT THAT THE OIL HOLES WILL BE PARTIALLY RESTRICTED TO THE SERIOUS DETRIMENT OF THE OIL FLOW AND CAPACITY.

Field experience indicates that this has happened in a number of instances of assembly either through "rushed work" or the mechanic not being aware that this gasket can be installed backwards. Big end failure can result from such assembly.

The fitting is easily accessible on the B40SS90 models and access can be gained on the C15SR Roadster and C15S Scrambler by removing the engine skid plate. It is recommended that this inspection be performed on all salesfloor models as well as on all such models coming into your shops for service.