

## from BSA Incorporated Service Dept.

Speed Bulletin #20

May 15, 1964

## TACHOMETER DRIVE FOR 1962-63 A50 AND A65 MODELS

A tachometer drive can be assembled on the Royal Star engines when it is desired for road or competition riding.

## PARTS REQUIRED:

QUANTITY	PART NO.	DESCRIPTION	LI	ST PRICE
1	68-218	Crankcase Inner Cover	\$	36.00 A
1	68-310	Oil Pump Drive Spindle		1.80 A
1	68-586	Tachometer Drive Pin		2.16 A
1	68-585	Tachometer Drive Nipple		1.80 A
1	68-588	"O" Ring Seal		.18 A
1	68-589	Gasket		.06 A
2	67-716	Nipple Screw	(.09 ea.)	.18 A

See Speed Bulletin #11 for part numbers and prices on Tachometer, Tachometer Cable and Mounting.

The above parts are available now and can be ordered from our Parts Department in the usual manner.

Walter Brown
Service Manager

ALL PRICES SUBJECT TO CHANGE WITHOUT NOTICE

