

For BSA and ARIEL Dealers

Service Bulletin #141

REVISED: February 8, 1965

A65 - A50 MODEL SERVICE AND REPAIR INSTRUCTIONS

Instructions on Servicing and Repairing the new 650cc and 500cc Twin Cylinder Models are given in the A50 - A65 Model Instruction Manual (Part No. 00-4096) which is furnished with each new motorcycle.

This Instruction Manual contains technical data, information on the controls, running-in details, lubrication specifications, routine maintenance, top end overhaul, information on the carburetor and electrical equipment as well as other general service hints.

The BSA Service Wall Charts No. MC-50, MC-51, MC-52, MC-53, MC-54, MC-55 and MC-56 are available in addition to the Instruction Manual. These Wall Charts give detailed instructions on dismantling and rebuilding the engine unit, the gearbox units, the front fork and the wheels.

Illustrations on the Service Charts show the most important procedures for dismantling and rebuilding the various components.

The Instruction Manual and Service Wall Charts are most helpful and should be readily available in your shop for quick reference when the occasion arises. Order your requirements according to the numbers shown.

There is no other Service literature in the form of a Dealer's Service Manual on the A50 and A65 Models.

Walter Brown,
Service Manager