

HINTS AND TIPS ON —SERVICE—

For **BSA** and **ARIEL** Dealers

Service Bulletin # 96

November 30, 1960

"A" & "B" MODEL SPEEDOMETER DRIVES
& 1960 SUPER ROCKET TACHOMETER DRIVES

To remove a tendency for oil to pass along the drive cables and into the speedometer and tachometer heads, the clearances at the drive shafts and the drive shaft housings have been reduced.

When the above trouble is experienced, new parts may be required for the speedometer drive at the gearbox or at the tachometer drive at the engine timing case.

PARTS REQUIRED FOR:

SPEEDOMETER DRIVE


| | | |
|---|----------|--------------------------------|
| 1 | #65-3396 | Speedometer driveshaft housing |
| 1 | #67-3175 | Speedometer driveshaft |

PART REQUIRED FOR:

TACHOMETER DRIVE

| | | |
|---|---------|-------------------------------|
| 1 | #42-165 | Tachometer driveshaft housing |
|---|---------|-------------------------------|

Yours very truly,
BSA Incorporated



Walter Brown
Service Manager

WB:ah