

HINTS AND TIPS ON — SERVICE —

For **BSA** and **ARIEL** Dealers

Service Bulletin #28

September 6, 1962

SERVICING THE FRONT FORKS ON A50 - A65 MODELS

The attached Service Bulletin #28 covers the servicing of the Front Forks on the Super Rockets -- Golden Flash -- "500" Flash -- Shooting Star and Gold Star Models.

The information and instructions in this Service Bulletin pertains to the A-50 and A-65 Models as well, except the fork springs and fork shafts are different. The Part Number is 68-5040 for the springs and the Part Number is 68-5030 for the shafts.

The fork oil seals, circlips, shims and bushings in the A-50 and A-65 Models are identical to those in the Models listed above and the tools listed in the attached Service Bulletin are all that is required to service the forks on the new Models.

Front Fork Oil Capacity -- per leg -- $6\frac{1}{2}$ oz. U. S. Measure.

BSA INCORPORATED

Walter Brown

WALTER BROWN
Service Manager

WB/jc
Attachment: S.B. #28