

JANUARY, 1961.



## PARTS SERVICE BULLETIN

No.G.C.8.

### C15 SCRAMBLER CRANKPIN.

A new crankpin with larger diameter connecting rod bearing has been fitted to all Scrambles Models after Engine No.C15S-2112.

Only the complete flywheel assembly is fully interchangeable with the earlier pattern and the part numbers affected are as follows:-

<u>Old Part No.</u>	<u>Description.</u>	<u>New Spares No.</u>
40-406	Flywheel assembly complete.	181 40-463
40-407	" " D/S	153 40-464.
40-404	" " G/S	151 40-466
40-47	Connecting rod.	142 40-472.
41-53	Crankpin	<del>132-41-149</del> 41-159
40-63	Gudgeon pin bush	121 40-475.

Individual replacement parts will continue to be available for earlier machines but complete flywheel assembly 181 40-463 will be supplied when complete replacement is required.