



JULY, 1961.

## **PARTS SERVICE BULLETIN**

No. G.A.13.

MID SEASON CHANGES 'A' GROUP.

The following mid season changes have been introduced.

1. Clutch push rod No. 11242-3274 has been introduced to replace No. 11265-3940.
2. Flywheel bolt No. 10667-1213 late 3 per set, now 2 per set with a new bolt No. 10667-1215 for oil tube location.
3. The driving peg hole in crankcase breather No. 12967-987 has been re-positioned to improve breathing at high engine speeds.

Latest parts will be supplied against all future orders received and are fully interchangeable with originals. Please amend your Stores records.