



BSA

SPEED & SPORTS **PARTS**



from  **BSA Incorporated Service Dept.**

Speed Bulletin #24

October 16, 1964

MORE R.P.M. - MORE POWER & SPEED!

**OVERSIZE INTAKE VALVES - RACING VALVE
SPRINGS - ALLOY VALVE COLLARS**
For 1954 to 1963 A10 Rocket Engine

<u>QUANTITY</u>	<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
2	67-961	Oversize Intake Valve (Valve head dia. 1½")	\$ 8.10 A ea.
4 pr.	B613	S & W Racing Valve Springs	2.74 B pr.
4	67-1349	Alloy Valve Collar	.96 A ea.
4 pr.	65-1848	Alloy Valve Collar Keepers	.96 A pr.

INSTRUCTIONS:

1. Increase inlet port at valve seat to 1-3/8" and polish to a mirror finish.
2. Re-face valve seat and grind in the valves for a perfect seat.
3. Shim valve springs to 1-5/16" solid height when valves are assembled in the cylinder head.

We have the above items in stock. Order a supply of these Speed Parts now and sell your A10 Rocket customers a SPEED JOB!

Walter Brown
Walter Brown,
Service Manager

