

B.S.A. CYCLES Ltd.

(Proprietors: The Birmingham Small Arms Co. Ltd.)

SERVICE SHEET No. 4.

"SERVICE."

May, 1930.

TANKS.

Nickel and chromium plated tanks must not be cleaned with metal polish. The surface of the plating can be restored by rubbing with a dry rag upon which has been sprinkled a small amount of Sheffield lime, after which the tank should be polished with a chamois leather.

Dented tanks cannot be replated.

Saddle tanks fitted to certain of our later productions are not interchangeable with earlier types of tanks, and cannot therefore be fitted to machines other than those for which they are intended.

When ordering a replacement petrol tank for 1929 2.49 or 1.74 h.p. model state whether B.S.A. or John Bull knee grips are fitted.

When ordering a replacement petrol tank with a screwed filler, state the number of threads per inch, i.e., 16, 20 or 24. This is important.