

May 1957.



PARTS SERVICE BULLETIN

No.G.A.1.

A.10 Road Rocket

In order to accommodate the increased power developed, the base of the cylinder has been increased in thickness.

This change takes place on and after engine No.CA10R 4182.

The new barrel can be used on engines prior to the above number providing that new fixing studs 67-1214 (9) and Tappet securing screw 67-949 are used also.

Part numbers of the assembled Crankcase complete with studs are also affected.

Old and new part numbers are as follows:

<u>OLD No.</u>	<u>DESCRIPTION.</u>	<u>NEW No.</u>
67-1074.	Cylinder Barrel.	67-1210.
67- 74.	" " Stud.	67-1214.
67- 276.	Tappet Securing Screw.	67-949.
67-1085. +	Crankcase Assembly D/S.	67-1079.
67-1087. +	" " G/S.	67-1080.
67-1089.	" " Complete.	67-1077.

+ Not supplied seperately.

C/R.D.

B.S.A.Motor Cycles Ltd.,
Service Dept.,
Birmingham 11.