

HINTS AND TIPS ON — SERVICE —

For **BSA** and **ARIEL** Dealers

Service Bulletin #181

February 5, 1965

K-1 MODEL SERVICE TOOLS

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>NET PRICE</u>
61-3721	Clutch Centre Extractor	\$ 5.34
61-3723	Valve Spring Compressor	1.83
61-3725	Piston Ring Slipper Complete	1.98
61-3727	Magneto Flywheel Extractor & Crankshaft Cap	1.98
61-3728	Crankshaft Primary Driving Pinion Extractor	3.81
61-3733	Crankshaft Pinion Extractor	1.98
61-3735	Valve Grinding Tool	.61
61-3737	Valve Guide Punch	1.37
61-3739	Stripping and assembly tools for conn rod and flywheel assembly	17.38
61-3738	Fork Spring Removal Tool	3.81

CAUTION: Do not attempt to remove the magneto flywheel without the use of the special extractor, part number 61-3727. A claw type extractor will distort the magneto flywheel and result in faulty ignition.

NOTE: You must put the cap supplied with the extractor between the end of the crankshaft and the point of the extractor screw to prevent damage to the threads on the crankshaft.

Walter Brown
Walter Brown,
Service Manager