



BSA INCORPORATED • 639 PASSAIC AVENUE • NUTLEY, NEW JERSEY 07110 • TELEPHONE (201) 667-5600  
EASTERN STATES DISTRIBUTOR FOR BSA MOTORCYCLES / A SUBSIDIARY OF THE BIRMINGHAM SMALL ARMS COMPANY, LTD. OF ENGLAND

---

**despatch to all dealers:**

SERVICE BULLETIN #45-69

September 25, 1969

FROM: Walter Brown, Service Manager

SUBJECT: NEW NYLON LINED CLUTCH CABLE - A75R3 MODEL

Clutch cable No. 60-1946 is now superseded by a new nylon lined cable No. 60-2445 to improve clutch action and to provide longer life.

LUBRICATION

Graphited oil only should be used to lubricate the cable.

GREASE MUST NOT BE USED.