

HINTS AND TIPS ON — SERVICE —

For **BSA** and **ARIEL** Dealers

Service Bulletin #162

May 27, 1964

SUBJECT: A65-2L LIGHTNING AND A50-2C CYCLONE MODELS

REAR MUDGUARD RAIL AND BRACE

The early shipments of A65-2L Lightnings with engine numbers up to A65D-676 and A50-2C Cyclones with engine numbers up to A50-236 were not equipped with rear mudguard rails and braces.

The BSA Factory is supplying us with the rails and braces for the two models shown above only. They are not supplying them for the 650cc Spitfire Hornet or the 500cc Cyclone Competition Models.

We will send you mudguard rails and braces for the two models you may have received without them. Please fill in the attached order blank and write in the engine numbers on the machines for which they are required and mail it back right away marked to my attention and we will make shipment on a free of charge basis.

Instructions for assembly will be included with each shipment.

Walter Brown

Walter Brown
Service Manager

WB/jc
Attachment: