



BSA INCORPORATED • 639 PASSAIC AVENUE • NUTLEY, NEW JERSEY 07110 • TELEPHONE (201) 667-5600
EASTERN STATES DISTRIBUTOR FOR BSA MOTORCYCLES / A SUBSIDIARY OF THE BIRMINGHAM SMALL ARMS COMPANY, LTD. OF ENGLAND

despatch to all dealers:

SERVICE BULLETIN #30-69

July 2, 1969

FROM: Walter Brown, Service Manager

SUBJECT: Correct Assembly of Oil Sump Cover-A75 Rocket 3 Model

The shape of the sump cover is designed to form a well around the oil-pump scavenge pipe.

If the cover is fitted the wrong way round, it is liable to block off the scavenge pipe, thus preventing the return flow of oil to the tank.

Care should therefore be taken to see that the cover is correctly refitted after removal.