

HINTS AND TIPS ON — SERVICE —

For **BSA** and **ARIEL** Dealers

Service Bulletin #128

October 19, 1962

C15-SS-80 AND B40-SS-90 MODELS PETROL TANK MOUNTING

A number of C15-SS-80 and B40-SS-90 machines left the Factory fitted with petrol tank mounting rubbers which were harder than specified. Wherever possible these rubbers should be replaced before the machines are put into service also replaced on machines that have been recently sold.

We urge you to replace the petrol tank mounting rubbers with the softer ones as they will provide a better cushion mounting and prevent tank failures.

Supplies of replacement rubbers are available now and can be ordered from our Parts Department in the usual manner.


Parts required for each machine:

3 -- 40-8046 Petrol Tank Mounting Rubbers.

You may return the original mounting rubbers for credit. Please send a CLAIM TAG in with them completely filled out.

We thank you for your cooperation.

BSA INCORPORATED



WALTER BROWN
Service Manager

WB/jc