

HINTS AND TIPS ON

SERVICE

For **BSA** Dealers

from **BSA** Incorporated, 639 Passaic Avenue, Nutley, N. J.

Service Bulletin #206

February 14, 1966

SUBJECT: REAR WHEEL SPROCKETS FOR 1966 A50 and A65 MODELS

All 1966 A50 and A65 Models are equipped with the "bolt on" type of sprocket. It bolts on a flange which is part of the brake drum. Sprockets can be interchanged to obtain a combination of gear ratios for various types of operation.

A selection of New Rear Wheel Sprockets are available as listed below:

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>DEALER NET</u>	<u>LIST PRICE</u>
B657-48 Tooth	Rear wheel sprocket- alloy	\$10.50	\$15.75
B658-52 Tooth	Rear wheel sprocket- alloy	\$10.50	\$15.75
B659-56 Tooth	Rear wheel sprocket- alloy	\$10.50	\$15.75
B660-60 Tooth	Rear wheel sprocket- alloy	\$10.50	\$15.75
B661-64 Tooth	Rear wheel sprocket- alloy	\$10.50	\$15.75

Earlier Model "Bolt on" Rear Wheel Sprockets will not fit on the 1966 Models.

A selection of standard Gear Box Sprockets are available as listed below:

For All A50- A65 Models 1962 to 1966

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>DEALER NET</u>	<u>LIST PRICE</u>
68-3074	Gear Box Sprocket -16 T	\$2.70	\$5.40
68-3072	Gear Box Sprocket -17 T	\$3.24	\$6.48
68-3093	Gear Box Sprocket -18 T	\$4.05	\$8.10
68-3078	Gear Box Sprocket -19 T	\$4.05	\$8.10
68-3073	Gear Box Sprocket -20 T	\$3.60	\$7.20
68-3089	Gear Box Sprocket -21 T	\$4.50	\$9.00

These sprockets may be ordered from our Parts Department in the usual manner.

WB/jw

Walter Brown
WALTER BROWN
Service Manager

These prices are subject to change without notice.