



BSA INCORPORATED • 639 PASSAIC AVENUE • NUTLEY, NEW JERSEY 07110 • TELEPHONE (201) 667-5600
EASTERN STATES DISTRIBUTOR FOR BSA MOTORCYCLES / A SUBSIDIARY OF THE BIRMINGHAM SMALL ARMS COMPANY, LTD. OF ENGLAND

despatch to all dealers:

SERVICE BULLETIN #42-69

September 4, 1969

FROM: Walter Brown, Service Manager

SUBJECT: FRONT FORKS TOPPING - 1969 "A" MODEL TWINS

If there is a noise in the front forks on the re-bounce when the fork legs are fully extended it can be eliminated by assembling springs rated at 26.5 LB/in.

The springs are available at our Parts Department and can be ordered under part no. 97-3678 fork spring - 2 required.