



DEALER PARTS and SERVICE BULLETIN

Hap Alzina 3074 Broadway Oakland 11, Calif.

INDEX

NO: 67
8 NOV 1961

= SUBJECTS =

CLUTCH ADJUSTMENT ON NEW MACHINES

ALL NEW B.S.A. MACHINES SHOULD BE INSPECTED FOR
CLUTCH CABLE ADJUSTMENT BEFORE BEING DELIVERED.

B.S.A. motorcycles, as received new in crates,
have the clutch springs under a slight tension
to eliminate the possibility of the clutch
plates "sticking".

This has been achieved by removing the front
brake cable during the packing process and assembling
the clutch cable in its place. When handlebars and
forks are removed from the machine for packing the
front brake lever WITH CLUTCH CABLE AFFIXED will be
fastened to the frame down tube and the knurled
adjustor on the clutch cable being so adjusted so
as to maintain a light tension on the clutch springs
thus leaving the plates separated slightly, just
enough to prevent "freezing" or "sticking".

In reassembly the forks will be installed in the
normal manner, the clutch cable removed from the
front brake lever and returned to its normal pos-
ition and the knurled adjustor is to be re-set to
the proper clearance which should complete the
matter of satisfactory clutch adjustment.