

HINTS AND TIPS ON —SERVICE—

For **BSA** and **ARIEL** Dealers

Service Bulletin #105

April 7, 1961

NEW BATTERY & CARRIER TWIN "A" MODELS

& 500cc SINGLE "B" MODELS

The Lucas battery PUZ7E has now been replaced on the above models by battery MLZ9E, which requires a new carrier.

The new battery and carrier are fitted to machines **after** the following frame numbers and are interchangeable in pairs. Supply of the earlier type carrier and battery will continue.

A7	GA7-8855
A7 SS	GA7-8929
A10	GA7-8437
A10 SR	GA7-8618
B33	GB33-498
Gold Star	CB32-9849

Part numbers affected are as follows:

<u>OLD PART NO.</u>	<u>MODEL</u>	<u>DESCRIPTION</u>	<u>NEW PART NO.</u>	<u>LIST PRICE</u>
42-4514	A7, A10, B33 & Gold Star	Batt. carrier comp.	42-4645	4.77
42-4519	A7SS, A10SR	Batt. carrier comp.	42-4645	4.77
19-1552 (PUZ7E)	A7SS, A10SR	Battery	19-1670 (MLZ9E)	13.25

Yours very truly,
BSA Incorporated

Walter Brown

Walter Brown
Service Manager

WB:ah

BSA Incorporated, 639 Passaic Avenue, Nutley N. J.