

HINTS AND TIPS ON — SERVICE —

For **BSA** and **ARIEL** Dealers

Service Bulletin #176

Dec. 7, 1964

A65 - A50 MODELS

FRONT FORK STEERING HEAD BEARINGS

The BSA Factory Service Manager advises that when crating new motorcycles for shipment all 1965 Models will have the Steering Head Ball Bearings put up in a small polythene bag together with a label indicating the quantity of ball bearings to be fitted in each bearing race.

This is a sample of the Label referred to above:

B.S.A. MOTOR CYCLES LTD.
BIRMINGHAM 11, ENGLAND.

MODELS A65 & A50

FIT 20 BALLS EACH TOP
& BOTTOM RACES. EXTRA
BALLS SUPPLIED AS SPARES

IMPORTANT: You must assemble the exact number of ball bearings in the top and bottom bearing races as specified on the label.

More or less balls assembled in the bearing races will have disastrous effects on the steering and handling of the motorcycles.

WALTER BROWN,
Service Manager