

HINTS AND TIPS ON —SERVICE—

For **BSA** *and* **ARIEL** *Dealers*

Service Bullerin No. 61

August 6, 1959

PROPER BREAK-IN OF 250 STAR SCRAMBLERS

C-15 SCRAMBLER

Deliveries of our 250 Star Scramblers are just commencing to come through from England. Orders are being filled as rapidly as possible.

We urge all dealers who sell a 250 Star Scrambler to remember that this -- like any other motorcycle -- must be put through a breaking in period.

THIS MOTORCYCLE must be carefully broken in -- over several hundred miles -- before it is ready for competition. Failure to put the machine through a proper break-in period at moderate speeds can lead to damage of both engine and transmission.

REFER TO SERVICE BULLETIN NO. 60 sent out by Mr. Walter Brown under date of July 21, 1959, relative to the necessity of increasing the oil level in the gear box. This applies to all C-15 models including the C-15 Scrambler.

Yours very truly,
BSA Incorporated