

HINTS AND TIPS ON — SERVICE —

For **BSA** and **ARIEL** Dealers

Bulletin #132

January 1, 1963

INSTRUCTION BOOKS & SERVICE MANUALS

<u>PART NUMBER</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
00-4078	1958-60 "A" Group	\$ 1.58
00-4061	1956-57 "A" Group	1.58
00-4012	1947-40 A-7 & A-7 S.T.	1.58
00-4013	1950-55 A-10 & 1951-55 A-7, A-7 S.S. & Road Rocket	1.58
00-4079	1958-62 "B" Group	1.58
00-4060	1956-57 "B" Group	1.58
00-4010	1946-55 "B" Group	1.58
00-4057	B32/34 Gold Star BB-DB	2.58
00-4069	B32/34 Gold Star DB-DBD	2.58
00-4081	Model C15, C15T, C15S, SS80, B40, SS90	1.58
00-4058	1956-57 C12	1.58
00-4053	1954-55 C Group	1.58
00-4009	1938-53 C Group	1.58
00-4056	1956-60 D1 & D7	1.58
00-4036	Models D1 & D3	1.58
00-4065	1956-60 M Group	1.58
00-4096	A50, A65 Riders Instruction Book	1.58
00-4032	Comprehensive Manual - Post War Models	9.84
00-4082	Model C15	3.00

WB/jc

Walter Brown
Walter Brown
Service Manager

This Bulletin replaces Service Bulletin #97.