



JUNE 1972

No. 17/72

Service sheet

'B' GROUP MODELS

REAR CHAIN OILERS

B.S.A. Motor Cycles Limited,
Service Department, Armoury Road,
Birmingham, B11 2PX.

Rear chain oilers were not fitted to 'B' Group models from 1971. The feed was blanked off with bolt, part number 14-6102/004, and a fibre washer, part number 66-7518. Parts Service Bulletin No. GB25 (March 1971, Page 2), made reference to these amendments.

Should owners of earlier models wish to alter their machines to conform with the later specification, the chain oiler can be removed and the orifice blanked off as described.

If the chain oiler is retained, the stud, part number 21-1985, is superseded by bolt part number 70-9217. This need be changed only if a replacement is necessary.