



BSA

SPEED & SPORTS PARTS



from **BSA** Incorporated Service Dept.

Speed Bulletin #27

January 4, 1965

18T GEARBOX SPROCKET
FOR A50 AND A65 MODELS

The Factory has made available at our request an 18 tooth gearbox sprocket to make it possible to obtain suitable overall gear ratios for different running conditions.

EXTERNAL GEAR RATIOS WHEN THE 18T SPROCKET IS ASSEMBLED

<u>REAR WHEEL SPROCKET</u>		<u>GEAR RATIO IN TOP SPEED</u>
42T	=	4.83 to 1
46T	=	5.29 to 1
50T	=	5.75 to 1
51T	=	5.86 to 1
52T	=	5.98 to 1
56T	=	6.44 to 1
58T	=	6.67 to 1
60T	=	6.90 to 1

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
68-3093	18T Gearbox Sprocket	\$8.10 A

We have this sprocket in stock now. Order according to Part Number shown.

Walter Brown
Walter Brown,
Service Manager

ALL PRICES SHOWN SUBJECT TO CHANGE WITHOUT NOTICE

