



JUNE, 1958.

SERVICE SHEET

No. 52.

A & B Groups.

Brake Operating Levers.

In order to improve brake operation, the angle of the square hole in the lever has been modified, the rear lever retaining the same part number and the front lever being replaced.

Modified levers and cables are fitted to machines on and after the following frame numbers.

A Group - FA7-5600.

B Group - FB31-2153.

Old and new part numbers are detailed below.

<u>Old No.</u>	<u>Description.</u>	<u>New No.</u>
42-5854.	Ft. brake lever.	42-5882.
42-6317.	Rear " " (modified).	42-6317.
42-8726.	Ft. brake cable (7").	42-8738.
42-8732.	" " " (8").	42-8740.
42-8735.	" " " (7" Western).	42-8742.
42-8729.	" " " (8" ").	42-8744.

Old type cables will still be available, but if the new lever 42-5882 is fitted as replacement of 42-5854, the equivalent front cable must also be used.