HINTS AND TIPS ON SERVICE

For BSA Dealers

from BSA Incorporated, 639 Passaic Avenue, Nutley, N. J.

Service Bulletin #238

January 4, 1967

SUBJECT: REAR WHEEL SPROCKETS FOR 1967- B44 VICTOR MODEL.

The 1967 B44 VICTOR Models are equipped with a "bolt on" type sprocket that has different dimensions than the 1966 rear wheel sprockets.

A selection of New Rear Wheel Sprockets are available now as listed below to obtain a combination of over-all gear ratios for various types of operation.

PART NO.	DESCRIPTION	DEALER NET	LIST PRICE
В666	52T Rear Wheel Sprocket (Alloy)	\$10.50	\$15.75
B667	56T Rear Wheel Sprocket (Alloy)	\$10.50	\$15.75
В668	60T Rear Wheel Sprocket (Alloy)	\$10.50	\$15.75

These sprockets can be ordered from our Parts Department in the usual manner.

WB/jw

Walter Thorn WALTER BROWN
Service Manager

Prices shown are subject to change without notice.