



BSA INCORPORATED • 639 PASSAIC AVENUE • NUTLEY, NEW JERSEY 07110 • TELEPHONE (201) 667-5600
EASTERN STATES DISTRIBUTOR FOR BSA MOTORCYCLES / A SUBSIDIARY OF THE BIRMINGHAM SMALL ARMS COMPANY, LTD. OF ENGLAND

despatch to all dealers:

SERVICE BULLETIN #17-69

April 25, 1969

FROM: Walter Brown, Service Manager

SUBJECT: Rocker Box Covers - A75R-3 Model.

The inlet rocker box cover and the exhaust rocker box covers are different and are not interchangeable.

CAUTION:

The covers can be assembled in the wrong location, however, there is interference at the rockers and it is possible that one or more of the valves will be held open when the covers are assembled incorrectly.

The rocker box covers can be identified by the numbers on the under side - No. E-6564 is for the front exhaust rocker box and No. E-6563 is for the rear inlet rocker box, so be sure they are re-assembled accordingly when they are removed to check the tappets.