

HINTS AND TIPS ON — SERVICE —

For **BSA** and **ARIEL** Dealers

Bulletin #118

April 12, 1962

B40-SS-90 MODEL - CARBURETOR MAIN JET

It has been reported that carburetors on some B-40-SS-90 Models are equipped with a #160 Main Jet.

This small size Main Jet is on the lean side and may result in discoloration of the exhaust pipe and possibly piston seizure.

It is recommended that the #160 Main Jet be replaced with a number #220 Main Jet to obtain proper gas mixture and maximum speed.

BSA Incorporated

Walter Brown

WALTER BROWN
Service Manager

WB/jc