

HINTS AND TIPS ON

SERVICE

For **BSA** Dealers

from **BSA** Incorporated, 639 Passaic Avenue, Nutley, N. J.

Service Bulletin #251

April 26, 1967

SUBJECT: A50-A65 MODEL - FLYWHEEL BALANCING (STATIC)

The procedure for Static Balancing the Flywheel and Crankshaft Assembly is described in your 1967 500 and 650 Twin Work Shop Manual on Page B44.

The Balance Weights that are required to perform the job are illustrated also on Page 44 - Fig. B.73.

Our Parts Department has these Balance Weights in stock and can be ordered in the usual manner.

<u>DESCRIPTION</u>	<u>PART NO.</u>	<u>NET PRICE</u>
Flywheel Balance Weights =1 Set	61-3710	\$27.97

WB/jw

Walter Brown

WALTER BROWN
Service Manager