



BSA INCORPORATED • 639 PASSAIC AVENUE • NUTLEY, NEW JERSEY 07110 • TELEPHONE (201) 667-5600
EASTERN STATES DISTRIBUTOR FOR BSA MOTORCYCLES / A SUBSIDIARY OF THE BIRMINGHAM SMALL ARMS COMPANY, LTD. OF ENGLAND

despatch to all dealers:

SERVICE BULLETIN #15-69

April 25, 1969

FROM: Walter Brown, Service Manager

SUBJECT: Rear Brake Adjustment - Model A75 Rocket 3

If the rear brake is incorrectly adjusted, it is possible for the brake pedal to foul the silencer before full pressure is applied.

First, set the pedal pin so that the pedal just clears the foot-rest.

Next screw up the brake rod wing nut until the wheel locks, then release the wing nut just enough to ensure that the wheel is free to revolve.