

HINTS AND TIPS ON — SERVICE —

For **BSA** Dealers

from **BSA** Incorporated, 639 Passaic Avenue, Nutley, N. J.

Service Bulletin #203

December 17, 1965

IMPORTANT - ASSEMBLY INFORMATION ON 1966 A50 and A65 MODELS

SUBJECT: FRONT MUDGUARD CENTER STAYS

These Front Mudguard Center Stays are now made as a "stamping" with a lipped edge for positive strength and must be attached outside of the Mudguard Bracket on the top end and must be assembled on the inside of the Brake Anchor Lug at the bottom end.

FAILURE TO ASSEMBLE THE MUDGUARD CENTER STAYS AS INSTRUCTED ABOVE MAY RESULT IN A STRESS ON THE STAY AND MUDGUARD WHICH WILL CAUSE BREAKAGE.

Walter Brown
WALTER BROWN
Service Manager

WB/mh