



MOTORCYCLES BICYCLES  
**BSA HAP ALZINA**



IMPORTERS

3074 BROADWAY

Oakland 11, California, U.S.A.

WESTERN UNITED STATES

**MEMO FROM "PARTS"**  
 IMPORTANT . . . . FILE IN YOUR PARTS BINDER

**PARTS BULLETIN #3**

**TO ALL DUNLOP MOTORCYCLE TIRE DEALERS:**

This is to inform all dealers that, due to insufficient sales volume, Dunlop is discontinuing production of all domestic motorcycle tires and the 4.75/5.00x16 domestic motorcycle tube. The V-18-19 and W-18-19 tubes will continue to be manufactured.

In addition to the above, England has also discontinued the manufacture of the following Universal Motorcycle tires.

2.375 x 19	5.00 x 16
2.375 x 21 (and tube)	4.75 x 16 (Rib)
3.50 x 21	

Although limited numbers of discontinued tires are in stock here and at Dunlop Corp. N. Y., they can no longer be considered as part of a 10 tire prepaid order. A new price list showing complete tire line now available will be issued shortly by Dunlop.

Dunlop has announced the availability of a 3.50 x 16 Sport tire. Price \$ 15.17 Dealer and \$ 21.65 Retail plus \$ .84 excise tax.

**GASKET SETS:**

Gasket sets are not listed in BSA parts catalogs however a complete list showing year and model can be found on page # 35 of our price book. Additional top end or "Decoke gasket sets" may be added as follows:

			Book List
00-3112	1954-57	A-7 S. Star	\$ 1.58
00-3113	1950-57	A-10 R. Rocket	1.56
00-3114	1957	M-21	1.52
00-3115	1954-55	C11, C11G	1.48
00-3116	1954-55	C10, C10L	1.48

**RIDER INSTRUCTION MANUALS:**

00-4009	1946-52	C-11	00-4053	1954-55	C11G, C10L
00-4010	1946-53	B-33, B-34	00-4056	1956-57	D-1, D-3
00-4011	1957	M-21	00-4057	1955-57	Catalina & Clubman
00-4012	1947-50	A-7, S. T.	00-4058	1956-57	C-12
00-4013	1950-53	A-10	00-4060	1956-57	B-33
00-4024	1950	Sunbeam	00-4061	1956-57	A-10, R. Rocket

**CLUTCH SLEEVES:**

Due to the 1/8" or so offset in chain line for enclosed rear chainguard of 1956-57 models another clutch sleeve was introduced. This sleeve is part # 42-3107 and has as mentioned more offset for full width hub models A-10, B-33 and Road Rocket. If 65-3873 early sleeve is used on late models premature wear of clutch chainwheel will result. 65-3873 sleeve is used on all A & B models without full enclosure rear chainguard.