



INDEX

NO. 96
11 SEPT 1963

50
mva

DEALER PARTS and SERVICE BULLETIN

= SUBJECTS =

A50 - A65 GEAR CHANGE

Hap Alzina 3074 Broadway Oakland 11, Calif.

D
E
A
L
E
R

E
N
G
I
N
E

N
O
S.

Our records indicate that you have received the above noted A50-A65 models during recent months.

The transmission gears on these models have been the subject of intensive study by the Engineering Department of BSA Motor Cycles, Ltd. with a mindful eye on the fact that engine power is continually increasing and further that many machines are locally tuned with a still further rise in power output, twin factors that contribute to maximum transmission stress. A decision has been reached by Engineering that the widest possible overload safety margin should exist within the transmission and accordingly a new, high-load-capacity, gearbox set of 5 gears has been introduced to supersede the present installation.

It is assumed that machines already delivered have been stress tested by actual service and thus require no further attention. However it is believed that our mutual interests would be best served by changing over any of the above noted units that still remain on your floor.

IF YOU WILL CIRCLE THE ENGINE NUMBERS STILL REMAINING ON YOUR FLOOR PROMPT ATTENTION WILL BE GIVEN TO IMMEDIATELY DESPATCHING THE NEW SUPERSEDING GEARSET.

FOR THE SAKE OF UNIFORMITY IN PROCEDURE THESE GEARS WILL BE BILLED YOUR ACCOUNT. AS SOON AS THE CHANGE HAS BEEN COMPLETED IT IS REQUESTED THAT THE SUPERSEDED GEARSET BE MAILED THIS OFFICE.

IMMEDIATELY UPON RECEIPT OF THE GEARSET REMOVED AN OFFSETTING CREDIT WILL BE ISSUED YOUR ACCOUNT TO BALANCE OUT THE GEARSET CHARGE AND A FURTHER CREDIT OF \$15.00 WILL BE ISSUED FOR THE CHANGE-OVER LABOR.

We should like to accomplish the field changeovers at the earliest possible moment and would appreciate your prompt attention.