

RIDER'S MANUALS
AND
DEALER'S SERVICE MANUALS

<u>PART NUMBER</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
00-4009	1946-53 "C" Group	\$1.58
00-4010	1946-55 "B" Group	1.58
00-4012	1947-50 "A" Group	1.58
00-4013	1950-53 "A" Group	1.58
00-4024	1951-54 S7 and S8 Sunbeam	1.58
00-4036	1950-57 D3 Bantam	1.58
00-4053	1954-55 C10L and C11G	1.58
00-4056	1954-64 D5 - D7 and D1 Bantam	1.58
00-4057	1954-57 BB and DB Gold Star	2.58
00-4058	1956-57 C12	1.58
00-4060	Up to 1957 B33	1.58
00-4061	1954 to 57 "A" Group	1.58
00-4069	1958-63 DB - DBD Gold Star B32 - B34	2.58
00-4078	1958-63 "A" Group	1.58
00-4079	1958 B33	1.58
00-4091	1959-63 C15, C15S, C15T, C15SS80, B40 and B40SS90	1.58
00-4096	1962-64 A50 and A65	1.58
00-4097	1963 Tina	1.58
00-4098	1962-63 Rocket Gold Star	1.58
00-4032	Comprehensive Dealers Service Manual - All BSA Post War Models	9.84
00-4047	500cc and 650cc A10 and A10R Dealers Service Manual	3.00
00-4082	C15, C15S, C15T, B40, B40T, SS80 and SS90 Dealers Service Manual	3.00

This Bulletin replaces Service Bulletin #132

Walter Brown
Walter Brown,
Service Manager