

# HINTS AND TIPS ON — SERVICE —

For **BSA** and **ARIEL** Dealers

Service Bulletin # 83

December 22, 1959

## SPROCKETS ON 1959-1960 MODELS

BSA MOTORCYCLES ARE FITTED WITH THE FOLLOWING SPROCKET COMBINATIONS AS STANDARD:

MODEL	ENGINE	CLUTCH CHAINWHEEL	GEARBOX	REAR WHEEL	TOP GEAR RATIO
A-10 SUPER ROCKET	21	43	19	42	4.53
A-10 SPITFIRE SCRAMBLER	17	43	16	42	6.64
A-10 GOLDEN FLASH	21	43	19	42	4.53
A-7 SHOOTING STAR	18	43	19	42	5.28
A-7 500 FLASH	18	43	19	42	5.28
B-34 CLUBMAN GOLD STAR	21	43	19	46	4.96
B-34 CATALINA SCRAMBLER	17	43	16	46	7.27
B-33 SPORTSMAN	20	43	16	42	5.64
C-15 STARFIRE SCRAMBLER	23	52	16	56	7.91
C-15 STAR	23	52	17	45	5.98
D-7 SUPER BANTAM	17	38	16	46	6.48
D-7A SUPER BANTAM	17	38	16	46	6.48
D-1 BANTAM	17	38	15	47	7.00

BSA INCORPORATED

*Walter Brown*

Walter Brown  
Service Manager

WB:jcf