

# HINTS AND TIPS ON — **SERVICE** —

For **BSA** and **ARIEL** Dealers

Service Bulletin #172

September 18, 1964

## IMPORTANT CORRECTION


### DISREGARD SERVICE BULLETIN 169.

#### MISUNDERSTANDING IN INFORMATION SUPPLIED BY BSA FACTORY

Correct assembly of C15 - B40 Model oil pressure release valve spring shown below:

To ensure the efficient functioning of the valve it is essential that the spring is correctly fitted, that is, with the larger diameter end seating inside the plug, as illustrated below:

BE SURE to assemble the oil pressure release valve springs as shown below on the machines that you may have already changed around according to Service Bulletin #169.



*Walter Brown*  
Walter Brown,  
Service Manager