



BSA INCORPORATED • 639 PASSAIC AVENUE • NUTLEY, NEW JERSEY 07110 • TELEPHONE (201) 667-5600
EASTERN STATES DISTRIBUTOR FOR BSA MOTORCYCLES / A SUBSIDIARY OF THE BIRMINGHAM SMALL ARMS COMPANY, LTD. OF ENGLAND

despatch to all dealers:

Service Bulletin No. 274

June 14, 1968

FROM: Walter Brown, Service Manager

TIPS ON CONCENTRIC CARBURETTER THROTTLE SLIDES

To prevent the throttle slides from sticking:

1. Do not over tighten the Air Lever Friction Screw.
2. Be careful that the Air Lever Cable does not become kinked.
3. Avoid over tensioning the Air Slide Cable and be sure it is operating freely. Lubricate frequently.

It is very important that these precautions be taken when setting up and servicing motorcycles equipped with Concentric Carburetters.

We urge you to warn your customers about tightening the Air Lever friction Screws to tight and caution them not to kink the Air Lever cable and to be sure it is lubricated frequently and operates freely.