

HINTS AND TIPS ON — SERVICE —

For **BSA** and **ARIEL** Dealers

Service Bulletin #121

May 14, 1962

"RUNNING IN" THE NEW A-65 MODEL

The pistons in the New A-65 Models are fitted with a minimum of clearance to assure quiet running engines so it is MOST IMPORTANT that you take the following precautions when you prepare a new machine for delivery and turn it over to the new owner.

1. Assemble a #320 Main Jet in the carburetor and run the machine with this richer jet during the "Running In" period. Reassemble the original main jet after the "Running In" has been completed.
2. Mix approximately four (4) ounces oil in each tankful of gasoline during the "Running In" period. Bardahl or Wynn's oil is recommended.
3. Caution the owner of a new A-65 Model that he MUST NOT ride the machine fast or exceed one-third throttle in any gear during the early stages of the "Running In" period -- 1000 to 1500 miles. Read the directions on page 13 in the Instruction Book for "Running In".

When these precautions are taken, there will be less chance of experiencing piston seizures.

Walter Brown

Walter Brown
Service Manager

WB/jc