

# HINTS AND TIPS ON —SERVICE—

For **BSA** and **ARIEL** Dealers

Service Bulletin #87

April 4, 1960

## REPLACEMENT SWITCH BUTTONS

### FOR 1960 "A" & "B" MODELS

			<u>Net Price</u>
1 - 07135	Engine Kill Button	(Red)	\$ .09
1 - 07136	Horn Push Button	(Green)	.09
1 - 07137	Dipper Switch Button	(Black)	.09

These replacement buttons may be ordered from our parts department in the usual manner.

Handlebars for new motorcycles are being packed at the factory with padding around the switches to prevent breakage during crating and uncrating so damage to the switch buttons will be eliminated on future shipments of motorcycles that we receive.

BSA Incorporated

*Walter Brown*  
Walter Brown  
Service Manager

WB:ah