

HINTS AND TIPS ON — SERVICE —

For **BSA** *and* **ARIEL** *Dealers*

Service Bulletin #68

August, 1959

BSA SUNBEAM SCOOTER

SPEEDOMETER CABLE

To allow an easier sweep to the speedometer cable, the cable clip under the rear drive case is now fitted beneath the head of the bolt instead of beneath the nut.

We recommend the adoption of the new cable layout for scooters already in service, to do this: --

- (1) Support the Scooter so that the rear wheel is clear of the ground and remove the rear wheel.
- (2) Remove the cable clip from the bolt and from the cable.
- (3) File a flat on the clip to match the flat on the bolt head.
- (4) Refit the clip to the cable with the bend on the clip towards the lefthand side, that is away from the wheel.
- (5) Replace the bolt with the clip under its head, and refit the nut and plain washer. Tap the clip towards the chain adjustor stud, in order to obtain maximum clearance between the cable and wheel.
- (6) Replace the wheel and check to ensure that the cable is at least 3/16" away from the wheel rim.

The time taken for this modification - approximately fifteen minutes.

BSA Incorporated

Walter Brown
Walter Brown
Service Manager

BSA Incorporated, 639 Passaic Avenue, Nutley N. J.