### HINTS AND TIPS ON

# =SERVICE =

## For BSA Dealers

from BSA Incorporated, 639 Passaic Avenue, Nutley, N. J.

Service Bulletin #232

October 12, 1966

#### TWIN MODELS WITH 4,00 X 18 TIRES

BUBJECT! 4.00 X 18 K70 REAR TIRE INFLATION PRESSURE

#### IMPORTANT:

The tire manufacturer stresses that for sustained speeds permitted by Turnpike and Pressway riding, the K70, 4.00 X 18 rear tire must be inflated to 24 POUNDS.

This requirement superscdes all previous published recommendations.

WR/jw

WALTER BROWN Service Manager