

HINTS AND TIPS ON

SERVICE

For **BSA** Dealers

from **BSA** Incorporated, 639 Passaic Avenue, Nutley, N. J.

Service Bulletin #223

May 19, 1966

SUBJECT: PREPARING NEW BATTERIES FOR SERVICE

The attached Lucas Service Information Sheet gives very Important Instructions on how to Service New Batteries before they are assembled in New Motorcycles and give a WARNING stating that you must syphon off EXCESS ACID otherwise the acid will over-flow and damage the Chrome and Paint.

We urge you to follow these Instructions carefully and pay particular attention to the WARNING so that it will not be necessary to replace Silencers & Exhaust Pipes because of Acid Stains.

"A word to the Wise is Sufficient."

WB/jw
Encl.

Walter Brown
WALTER BROWN
Service Manager