



BSA

SPEED & SPORTS PARTS



from **BSA** Incorporated Service Dept.

Speed Bulletin #22

July 8, 1964

CARBURETOR VELOCITY TUBE FOR A65-2L LIGHTNING MODELS

Velocity tubes are available to assemble on twin carburetor Lightning models to obtain maximum top speed performance when the air cleaners are removed. Assemble #280 main jets in the carburetors when the velocity tubes are installed.

<u>PART NUMBER</u>	<u>DESCRIPTION</u>	<u>LIST PRICE</u>
389/089	CARBURETOR VELOCITY TUBE (Silver-grey finish)	\$3.00 A
376/100	#280 Main Jet	.63 A

These items are in stock now and can be ordered from our Parts Department in the usual manner.

Walter Brown

Walter Brown
Service Manager

ALL PRICES SUBJECT TO CHANGE WITHOUT NOTICE

