

HINTS AND TIPS ON —SERVICE—

For **BSA** and **ARIEL** Dealers

Service Bulletin #102

April 5, 1961

MODEL C15 OIL CONTROL

To improve oil control, a tapered compression ring is now being fitted in the center groove of the piston on all machines after the following engine numbers:


C15	Standard Model	C15 24401
C15S	Scrambles Model	C15S 2171
C15T	Trials Model	C15T 1182

Tapered rings for earlier machines may be ordered from our parts department according to the part numbers shown below:

40-95	Taper piston ring	(Standard)
40-96	Taper piston ring	(+ $\frac{1}{2}$ m.m.)
40-97	Taper piston ring	(+ 1 m.m.)

The ring must be fitted with the face marked "T" upward.

Yours very truly,
BSA Incorporated


Walter Brown
Service Manager

WB:ah