

HINTS AND TIPS ON — SERVICE —

For **BSA** and **ARIEL** Dealers

Service Bulletin #100

March 29, 1961

PLATINUM MAGNETO CONTACT POINTS FOR SUPER ROCKET ENGINES

Platinum contact points have been made available to assure positive ignition current at high engine R.P.M.

It is recommended that the Platinum Points be assembled in the early Super Rocket magneto when there is mis-firing at high speed or when difficulty is experienced in obtaining high speed performance.

The platinum points are supplied in a set consisting of the breaker arm and contact point screw, also supplied in a complete Contact Breaker Assembly and can be ordered from our Parts Department according to the numbers listed below.

<u>Part Number</u>	<u>Description</u>	<u>List Price</u>
54440863	Contact Breaker Assy. Complete	9.15
54440890	Contact Point Set	5.85

The 1961 Super Rocket Magnetos are equipped with Platinum Contact Points.

Yours very truly,
BSA Incorporated

Walter Brown
Walter Brown
Service Manager

WB:ah