HINTS AND TIPS ON

=SERVICE=

For BSA Dealers

from **BSA** Incorporated, 639 Passaic Avenue, Nutley, N. J.

Bulletin #216

April 26, 1966

SUBJECT: D-175 Model-Head Lamp Conversion

The standard Wipac Head Lamp has not been approved by some State Motor Vehicle Departments, therefore it may be necessary to convert to a Lucas Head Lamp to get the D175 Model approved at Motor Vehical Inspection.

The following parts are required to make the conversion:

1	516828	Headlight unit
1	534343	Chrome rim
1	312	bulb
1	988	bulb
1	144921	Chrome rim screw
1	554602	Main bulbholder
1	555910	Terminal sleeve
1	554710	Pilot bulbholder
1	554354	Ring, seating bulbholder

The parts shown above may be ordered from our parts department in the usual manner.

The Wipac parts may be returned for credit provided they are not damaged and can be sold as new.

Walter Brown

Service Manager