

## despatch to all dealers:

SERVICE BULLETIN NO. 290

November 25, 1968


FROM: Walter Brown, Service Manager

SUBJECT: A75 BSA Maintenance Handbook

### WARNING!

On certain early printings of the Rocket 3 Maintenance Handbook, Page 14, which are packed with the motorcycles, the illustration showing the fitting of the oil filter cartridge is incorrect.

The illustration below shows the correct manner in which to fit the oil filter cartridge.



### WARNING!

Be sure this is understood by all of your personnel and customers.