



FEBRUARY 1971

1/71

Service sheet

B.S.A. Motor Cycles Limited,
Service Department, Armoury Road.
Birmingham, B11 2PX.

1971 'A' AND 'B' GROUP
8" FRONT BRAKE MODELS

When setting up 1971 models out of the crate, it is important, when adjusting the front brake, to ensure that the front brake cable adaptor is correctly located in the abutment bush at the brake plate end of the cable.